












PLATE 18 - SEA WATER INTRUSION MONITORING WELLS



Note: Each sea water intrusion monitoring well contains two or more piezometers

LEGEND

-  Study Area Boundary
-  Groundwater Basin Boundary
-  Groundwater Subbasin Boundary
-  Hydrologic Area (HA) and Subarea (HSA) Boundaries
-  Bedrock Outcrop Within Groundwater Basin
-  Fault, dashed where approximately located, queried where inferred, dotted where concealed
-  Thrust Fault, dashed where approximately located, saw-teeth on upper plate, dip of fault plane between 30 and 80 degrees
-  Buried bedrock step of uncertain origin, ball on lower side
-  Buried monocline, arrow showing direction and width of downwarp
-  Syncline, showing trace of axial surface, dashed where approximately located, dotted where concealed

Scale in Miles
Copy of document found at www.NoNewWipTax.com