Oceano Community Services District

1655 Front Street, P. O. Box 599, Oceano, CA 93445 (805) 481-6730 FAX (805) 481-6836

Board of Supervisors
County of San Luis Obispo
County Government Center
San Luis Obispo, California 93408

February 8, 2012

RE: Sea Water Intrusion In Oceano

Dear Sirs,

The Oceano groundwater supply is not threatened with seawater intrusion. We are aware that there has been information provided to the public that Oceano's groundwater supply is threatened by seawater intrusion. The incident in 2009 exhibited characteristics of saltwater intrusion but it has since to be repeated and it also should be noted that the well in question was in great disrepair. This was corrected by the county maintenance crew and at no time since has it exhibited anymore characteristics of seawater intrusion.

At the time that this sentry well was tested, there were significant external contaminants. The Board at the time was directed by its contracted engineer to take a position that the event was actually a benefit because it would elevate the priority level in case of any state water contractor allocation cutbacks. This same engineer is on contract with several San Luis Obispo agencies to which this information has been exploited to their benefit.

We normally would have accepted this without comment, but the level of exploitation of this anomaly has reached critical mass and is being quoted from everything from commercial development, other agencies needs and willful suspensions of the truth.

Sincerely,

MATTHEW G. GUERRERO
President

MARY LUCEY
Vice-President

RICHARD SEARCY
Director

FELMA HURDLE
Director

LORI ANGELLO
Director

TOM GEASLEN
Interim General Manager

attachments



SOURCE: Todd Engineers, 2010.

Z:\Projects\104220_NCMA\Fig7_SentryWells.mxd RS

01-Mar-2011

2010 Annual Monitoring Report
San Luis Obispo, California

GEI Consultants

Location of Sentry Wells

Northern Cities Management Area

APRIL 2011

FIGURE 7

Figure 8 - Depths of Sentry Wells



2010 ANNUAL MONITORING REPORT	GEI Consultants	DEPTHS OF SENTRY WELLS	
NORTHERN CITIES MANAGEMENT AREA		APRIL 2011	FIGURE 8

00-xxx-0000 Z:\GIS\Projects\...mxd XXX

Table 6b: Northern Cities Sentry Well Water Quality Data Summary

Well	Production Interval	Date	Depth to Water (feet)	Groundwater Elevation (feet NAVD)	Total Dissolved Solids (mg/L)	Chloride (mg/L)	Sodium (mg/L)
32S/13E-30F03	Screened from 305-372'	1/24/2011	12.67	10.64	650	46	36
		10/28/2010	NA	NA	650	46	37
		10/21/2010	6.62	16.69	NA	NA	NA
		7/26/2010	17.32	5.99	608	45	43.8
		4/27/2010	11.38	9.02	668	48	40.8
		1/28/2010	10.98	9.42	656	40	43.1
		10/19/2009	14.18	6.22	626	48	43.3
		8/19/2009	20.23	0.17	672	45	43.1
		5/12/2009	17.68	2.72	678	49	44.8
		3/27/1996	NA	NA	686	41	40
		6/7/1976	NA	NA	616	43	41
		1/19/1966	NA	NA	642	69	49
32S/13E-30N01	Screened from 15-40'	1/24/2011	8.18	7.35	870	180	100
		10/21/2010	9.99	5.54	890	190	120
		7/27/2010	8.97	6.56	917	200	130
		4/27/2010	6.14	7.36	808	150	130
		1/26/2010	4.90	8.60	902	210	155
		10/20/2009	6.53	7.00	828	200	159
		8/20/2009	6.71	6.82	835	160	150
		5/11/2009	6.03	7.50	960	180	175
32S/13E-30N03	Screened from 60-135'	1/24/2011	6.68	8.75	570	76	48
		10/21/2010	10.76	4.67	550	69	59
		7/27/2010	9.53	5.90	528	72	55.1
		4/27/2010	6.14	7.36	672	89	60.6
		1/26/2010	5.88	7.62	606	110	75.0
		10/20/2009	6.56	6.94	806	180	93.3
		8/20/2009	7.50	6.00	1,070	190	151
		5/12/2009	6.33	7.17	602	97	63.4
		3/27/1996	NA	NA	624	70	62
		6/7/1976	NA	NA	705	90	54
		1/21/1966	NA	NA	804	57	54
32S/13E-30N02	Screened from 175-255'	1/24/2011	3.67	11.76	1,050	50	60
		10/21/2010	10.42	5.01	1,040	48	52
		7/27/2010	10.02	5.41	777	57	67.6
		4/27/2010	5.26	8.27	800	93	71.9
		2/25/2010	1.72	11.78	1,000	48	71.4
	Confirmation Sample Collected from Pump Discharge at End of Purge:	2/25/2010	1.72	11.78	1,010	74	76.9
	Confirmation Sample Collected by Standard Method (Bailer):	1/26/2010	3.72	9.78	970	50	74.2
		10/20/2009	7.38	6.12	2,080	690	274
		8/20/2009	11.94	1.56	1,350	500	199
		5/11/2009	6.98	6.52	1,290	170	129
		3/27/1996	NA	NA	1,050	50	71
		6/7/1976	NA	NA	1,093	48	62
		1/21/1966	NA	NA	1,069	54	71
12N/36W-36L01	Screened from 227-237'	1/24/2011	17.61	8.68	890	41	55
		10/21/2010	20.75	5.54	910	38	76
		7/27/2010	21.18	5.11	707	36	64.2
		4/26/2010	15.94	8.06	860	42	70.3
		10/21/2009	17.72	6.28	856	38	72.0
		8/20/2009	19.16	4.84	890	39	78.0
		5/11/2009	17.68	6.32	832	63	83.8
		3/26/1996	NA	NA	882	35	66
		6/8/1976	NA	NA	936	38	72

Period of Elavated NA/CL

Table 6a: Northern Cities Sentry Well Water Quality Data Summary

Well	Construction	Top of Casing Elevation (feet NAVD)	Date	Depth to Water (feet)	Groundwater Elevation (feet NAVD)	Total Dissolved Solids (mg/L)	Chloride (mg/L)	Sodium (mg/L)	Potassium (mg/L)	Calcium (mg/L)	Magnesium (mg/L)	Bicarbonate (as CaCO3) (mg/L)	Sulfate (mg/L)	Nitrate (mg/L)	Total Kjeldahl Nitrogen (mg/L)	Boron (mg/L)	Fluoride (mg/L)	Iodide (mg/L)	Manganese (mg/L)	Bromide (mg/L)	Alkalinity, Total (as CaCO3) (mg/L)	Carbonate (as CaCO3) (mg/L)	Hydroxide (as CaCO3) (mg/L)	Specific Conductance (umhos/cm)	Iron (mg/L)	Bromide / Chloride Ratio	Chloride / Bromide Ratio
325/13E-36N03	Screened from 60-130' - 2-Inch diameter	15.43																									
	Wellhead renovation in 6/2010 added to the TOC elevation	1.90	1/24/2010	6.69	8.75	570	76	48	4.8	55	25	130	120	16	<1.0	0.12	0.2	<0.10	0.0068	1.7	130	<2.0	<2.0	900	<0.1	0.0224	45
	Pad elevation NAVD 88	13.53	10/21/2010	10.76	4.67	550	69	59	3.3	65	31	133	130	15	<1.0	<0.1	0.1	NA	<0.005	1.1	133	<10	<10	656	<0.1	0.0159	63
	TOC elevation prior to renovation (Approximate)	13.6	7/27/2010	9.53	5.90	528	72	55.1	3.41	68.7	31.0	139	130	15.0	< 0.10	0.0672	0.14	0.11	< 0.00500	1.3	139	< 1.0	< 1.0	660	< 0.100	0.0181	55
			4/27/2010	6.14	7.36	672	69	60.6	3.65	70.6	32.5	134	130	14.0	< 0.50	0.0779	0.18	0.11	< 0.00500	1.2	134	< 1.0	< 1.0	870	< 0.100	0.0135	74
			1/26/2010	5.88	7.62	606	110	75.0	4.53	77.6	34.3	126	130	14	1.4	0.0654	0.15	< 0.10	0.0130	1.3	126	< 1.0	< 1.0	990	0.653	0.0118	85
			10/20/2009	6.56	6.94	806	180	95.3	25.5	92.3	41.5	162	150	8.7	2.2	0.107	0.26	< 0.10	0.245	1.4	162	< 1.0	< 1.0	1,200	0.344	0.0078	129
			8/20/2009	7.50	8.00	1,019	190	151	51.6	112	44.2	139	130	16	3.4	NA	0.20	< 0.10	0.151	1.6	130	< 1.0	< 1.0	1,700	1.93	0.0084	119
			5/12/2009	6.33	7.17	602	97	63.4	3.96	72.9	32.2	122	120	NA	NA	NA	0.22	NA	24	1.2	122	< 1.0	< 1.0	900	2.24	0.0124	81
			3/27/1996	NA	NA	624	70	62	4	78	35	150	161	106.6	NA	0.13	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			6/7/1976	NA	NA	705	90	54	2.9	89	43	189	168	112.5	NA	0.09	0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			1/21/1958	NA	NA	804	57	54	3	132	59	410	290	1	NA	0.08	0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
325/13E-36N02	Screened from 135-255' - 2-Inch diameter	15.43																									
	Wellhead renovation in 6/2010 added to the TOC elevation	1.90	1/24/2011	3.67	11.76	1,050	50	60	6.4	120	49	190	490	0.24	<1.0	0.17	0.17	<0.10	0.064	<0.1	190	<2.0	<2.0	1,380	0.12	NA	NA
	Pad elevation NAVD 88	13.53	10/21/2010	10.42	5.01	1,040	48	52	3.5	100	45	181	460	0.16	<1.0	<0.1	<0.1	NA	<0.005	<0.3	181	<10	<10	1,377	<0.1	NA	NA
	TOC elevation prior to renovation (Approximate)	13.6	7/27/2010	10.03	5.41	777	57	67.6	7.31	141	58.5	190	470	0.3	3.5	0.138	< 0.10	0.11	0.102	0.28	190	< 1.0	< 1.0	1,500	3.43	0.0049	204
			4/27/2010	5.26	8.27	600	93	71.9	12.50	108	46.3	159	300	7.0	3.2	0.123	0.13	0.11	0.0775	0.7	159	< 1.0	< 1.0	1,100	3.27	0.0075	133
			2/25/2010	1.72	11.78	1,000	48	71.4	4.70	141	58.1	195	490	0.16	< 0.50	0.15	0.15	< 0.10	0.0093	0.16	195	< 1.0	< 1.0	1,500	3.30	0.0033	300
	Confirmation Sample Collected from Pump Discharge at End of Purge		2/25/2010	1.72	11.78	1,010	74	75.9	10.2	138	55.8	195	440	0.13	2.4	0.142	0.16	< 0.10	0.0579	0.24	195	< 1.0	< 1.0	1,400	1.69	0.0032	208
	Confirmation Sample Collected by Standard Method (Bailer)		1/26/2010	3.72	9.78	970	50	74.2	4.77	152	62.2	195	510	0.14	< 0.50	0.129	0.11	< 0.10	< 0.00500	0.16	195	< 1.0	< 1.0	1,500	< 0.100	0.0032	313
			10/20/2009	7.38	6.12	2,060	690	274	181	239	101.0	220	400	< 5.10	7.0	0.201	0.16	0.67	0.308	2.0	220	< 1.0	< 1.0	2,800	5.50	0.0029	345
			8/20/2009	11.54	1.96	1,356	500	199	80.2	133	49.0	199	220	6.4	6.5	NA	0.23	0.14	0.339	2.8	199	< 1.0	< 1.0	2,100	4.51	0.0056	179
Readings in Question			5/11/2009	6.98	6.52	1,290	170	129	52	137	66.9	178	470	NA	NA	NA	0.18	NA	0.126	0.56	176	< 1.0	< 1.0	1,800	3.24	0.0033	304
			3/27/1996	NA	NA	1,000	50	71	6.5	145	60	243	516	0.9	NA	0.23	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			6/7/1976	NA	NA	1,093	48	62	4.7	150	60	248	484	0	NA	0.13	0.7	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			1/21/1958	NA	NA	1,069	54	71	5	148	63	232	483	0	NA	0.12	0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
12N/06W-36L01	Screened from 227-237' - 2-Inch diameter	26.29																									
	Wellhead renovation in 6/2010 added to the TOC elevation	2.31	1/24/2011	17.61	8.68	890	41	55	5.1	99	38	160	400	0.50	<1.0	0.30	0.15	<0.10	<0.005	<0.1	160	<2.0	<2.0	1,200	<0.1	NA	NA
	Pad elevation NAVD 88	23.98	10/21/2010	20.75	5.54	910	38	76	3.6	120	47	169	400	0.39	<1.0	0.10	<0.1	NA	<0.005	<0.3	169	<10	<10	1,213	<0.1	NA	NA
	TOC elevation prior to renovation (Approximate)	24.0	7/27/2010	21.18	5.11	797	36	64.2	3.70	127	47.4	162	420	0.48	< 0.50	0.158	< 0.10	< 0.10	< 0.00500	0.11	162	< 1.0	< 1.0	1,100	< 0.100	0.0034	327
			4/26/2010	15.94	8.00	660	42	70.3	4.13	129	48.9	191	460	0.45	0.77	0.223	< 0.1	0.13	0.057	0.14	191	< 1.0	< 1.0	1,100	4.55	0.0033	300
			10/21/2009	17.72	6.39	836	38	72.0	4.64	131	48.2	192	430	0.49	0.84	0.150	0.12	< 0.10	0.0094	0.13	192	< 1.0	< 1.0	1,100	1.68	0.0034	292
			8/20/2009	19.16	4.84	830	39	78.0	4.21	139	48.1	184	390	0.49	0.56	NA	< 0.10	< 0.10	0.185	0.14	184	< 1.0	< 1.0	1,200	2.03	0.0036	279
			5/11/2009	17.68	6.33	832	63	83.8	4.65	111	45.4	204	330	NA	NA	NA	0.12	NA	0.551	0.22	204	< 1.0	< 1.0	1,300	4.02	0.0035	286
			3/26/1996	NA	NA	882	35	66	4.8	124	47	233	408	2	NA	0.24	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			6/8/1976	NA	NA	936	39	72	3.5	130	48	223	423	0.6	NA	0.15	0.7	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
12N/06W-36L02	Screened from 535-545' - 2-Inch diameter	26.19																									
	Wellhead renovation in 6/2010 added to the TOC elevation	2.31	1/24/2011	9.37	16.82	600	120	95	7.6	75	30	300	190	<0.05	2.3	0.39	0.18	1.31	0.13	0.53	300	<2.0	<2.0	1,270	1.40	0.0044	326
	Pad elevation NAVD 88	23.98	10/21/2010	19.77	6.52	770	120	130	7.6	89	44	275	160	<0.1	3.4	0.48	<0.1	NA	0.15	0.54	275	<10	<10	1,283	0.12	0.0043	222
	TOC elevation prior to renovation (Approximate)	24.0	7/27/2010	20.53	5.76	737	110	121	7.81	91.1	38.9	268	190	< 0.10	< 0.50	0.437	0.10	0.77	0.160	0.60	268	< 1.0	< 1.0	1,200	0.643	0.0073	138
			4/26/2010	9.24	14.76	720	100	116	6.89	85.4	32.4	215	210	1.8	0.77	0.387	0.2	0.28	0.167	0.7	215	< 1.0	< 1.0	1,100	3.870	0.0070	143
			10/21/2009	17.65	6.31	838	99	113	6.15	81.6	23.0	172	200	< 0.10	3.2	0.268	0.33	57	0.128	0.61	172	< 1.0	< 1.0	940	0.255	0.0062	162
			8/20/2009	19.15	4.85	783	100	131	6.66	99.8	36.8	290	190	< 0.10	3.8	NA	0.15	0.27	0.207	0.79	290	< 1.0	< 1.0	1,200	0.830	0.0073	133
			5/11/2009	14.35	9.62	775	120	132	7.24	84	28.7	254	180	NA	NA	NA	0.18	NA	0.426	0.78	254	< 1.0	< 1.0	1,300	0.918	0.0065	154
			3/26/1996	NA	NA	772	127	150	8.7	88	36	300	148	0.2	NA	0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
			6/8/1976	NA	NA	820	129	118	6.6	94	44	333	184	0	NA	NA	0.5	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
Oceano MW-Green	Screened from 110-130' - 3-Inch diameter	30.86																									
	Casing relative to concrete pad	-4.14	1/24/2011	106.59	-71.90	310	98	22	8.1	34	9.2	19.0	53	<0.05	<1.0	<0.1	0.2	4.42	0.4	0.63	19.0	<2.0	<2.0	480	10	0.0064	156
	Pad elevation above MSL, approximate	35.0	10/28/2010	NA	NA	290	81	26	9.3	64	11	160.0	68	<0.1	<1.0	<0.1	0.2	NA	0.55	0.56	160.0	<10	<10	520	38	0.0044	225
			10/21/2010	112.71	-81.85	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
	All elevations relative to MSL		7/26/2010	95.61	-64.75	438	85	34.3	1.93	61.7	30.4	30.0	210	< 0.10	< 0.50	0.0435	0.58	0.22	1.46	0.32	30.0	< 1.0	< 1.0	690	36	0.0038	288
			4/26/2010	63.90	-33.04	560	83	47.7	5.7	86.1	48.3	62	310	< 0.10	0.84	< 0.02	< 0.1	0.56	2.54	0.31	62.0	< 1.0	< 1.0	880	233	0.0037	268
			1/27/2010	43.71	-12.85	460	130	45.0	25.4	882	124	112	100	0.56	NA	< 0.0200	0.21	0.29	32.4	0.49	112.0	< 1.0	< 1.0	760	4,300	0.0038	265
			10/20/2009	29.20	1.66	362	93	39.6	2.92	19.2	45.1	78.8	110	< 0.10	< 0.50	0.0697	< 0.10	< 0.10	0.242	0.39	80.0	3.2	< 1.0	590	11.4	0.0042	236
			8/18/2009	24.85	6.34	420	160	48.4	3.37	49.9	20.4	17.6	54	< 0.10	1.1	NA	< 0.10	0.25	1.36	0.68	17.6	< 1.0	< 1.0	690	242	0.0043	233
			5/16/1983	15.80	15.06	668	39	40	NA	85	65	366	90	< 4	NA	NA	0.2	NA	0.01	NA	300	ND	ND	950	0.10	NA	NA
Oceano MW-Blue	Screened from 190-210' and 245-265' - 3-Inch diameter	30.91																									
	Casing relative to concrete pad	-4.09	1/24/2011	24.87	9.78	680	110	60	17	64	22	5.0	330	<0.05	<1.0	<0.1	0.22	0.96	0.16	0.31	11.2	6.2	<2.0	1,040	10.0	0.0038	355
	Pad elevation above MSL, approximate	35.0	10/21/2010	30.11	0.80	770	100	68	12	88	31	14.0	380	<0.1	<1.0	<0.1	0.28	NA	0.054	<0.3	14.0	<10	<10	1,163	2.2	NA	NA
			7/26/2010	24.74	6.17	783	130	80.1	8.58	142	42.0	2.8	450	< 0.10	< 0.50	< 0.0200	0.26	0.31	3.97	0.8	2.8	< 1.0	< 1.0	1,200	593	0.0059	169
	All elevations relative to MSL		4/26/2010	18.52	12.39	1,130	160	70.2	6.48	208	50.7	8.4	530	< 0.10	0.56	< 0.02	0.23	0.54	3.10	1.0	8.4	< 1.0	< 1.0	1,600	383	0.0061	163
			1/27/2010	22.06	8.85	1,740	430	55.6	4.59	282	43.0	< 1.0	660	< 0.10	< 0.50	0.0819	0.14	0.41	9.41	2.0	< 1.0	< 1.0	< 1.0	2,300	170	0.0047	215
			10/20/2009	27.50	3.41	2,250	1,000	19.5	2.40	487	22.5	5.0	410	< 0.10	0.93	0.0532	0.13	< 0.10	13.1	4.5	5.0	< 1.0	< 1.0	3,100	236	0.0045	322
			8/19/2009	24.65	6.26	302	150	93.2	16.7	23.9	12.1	3.0	4.0	< 0.10	1.3	NA	0.19	0.5	0.7	0.74	23.0	20.0	< 1.0	640	153	0.0049	303
			5/16/1983	13.30	17.61	840	90	90	NA	100	50	250	100.0	< 4	NA	ND	0.2	NA	0.14	NA	200.0	ND	ND	1,200	0.10	NA	NA
Oceano MW-Silver	Screened from 305-435' and 470-510' - 3-Inch diameter	30.85																									
	Casing relative to concrete pad	-4.15	1/24/2011	22.02	12.61	440	92	90	9.2	3.4	27	90	140	<0.05	<1.0	0.25	0.11	0.94	0.041	0.33	110	30	<2.0	810	2.2	0.0038	283
	Pad elevation above MSL, approximate	35.0	10/21/2010	23.11	1.74	460	90	110	15	6.8	32	94	140	<0.1	<1.0	0.2	0.1	NA	0.1	0.38	124	30	<10	868	3.5	0.0042	237
			7/26/2010	24.24	0.61	478	83	109	5.94	52.9	30.4	122.0	84	< 0.10	< 0.50	0.255	< 0.10	0.41	0.477	0.56	120.0	8.0	< 1.0	730	61.0	0.0067	148
	All elevations relative to MSL		4/26/2010	19.04	11.81	452	83	83	7.42	79.3	34.5	72.0	190	< 0.1	0.56	0.134	< 0.10	0.69	0.702	0.4	66.0	14.0	< 1.0	810	71.0	0.0048	208
			1/27/2010	21.05	9.8	498	71	92.2	10.6	92.9	39.1	13.0	230	< 0.10	< 0.50	0.323	< 0.10	0.20	0.604	0.29	51.0	38.0	< 1.0	780	84.4	0.0041	245
			10/20/2009	27.52	3.33	564	71	80.8	8.63	33.2	49.8	49.6	310	< 0.10	< 0.50	0.148	< 0.10	< 0.10	0.337	0.32	64.0	14.4	< 1.0	650	20.0	0.0045	222
			8/19/2009	29.34	1.51	522	160	148	71.6	95.2	8.42	50.0	3.5	< 0.10	1.7	NA	0.24	0.52	2.36	0.76	170	140	< 1.0	1,000	278	0.0042	237
			5/16/1983	-13.50	17.35	630	40	40	NA	90	50	330	80	< 4	NA	NA	0.1	NA	0.02	NA	330	ND	ND	900	0.05	NA	NA
Oceano MW-Yellow	Screened from 625-645' - 3-Inch diameter	30.89																									
	Casing relative to concrete pad	-4.11	1/24/2011	22.01	12.62	430	93	73	6	6.3	31	160	100	<0.05	<1.0	0.22	0.11	0.66	0.078	0.28	160	<2.0	<2.0	780	0.49	0.0034	286
	Pad elevation above MSL, approximate	35.0	10/21/2010	23.22	2.67	410	87	100	3.9	6.0	33	148	100	<0.1	<1.0	0.14	<0.1	NA	0.097	<0.3	148	<10	<10	796	0.66	NA	NA
			7/26/2010	25.56	5.39	446	94	93.0	8.81	10.2	32.0	38.4	120	< 0.10	< 0.50	0.142	< 0.10	0.32	0.196	0.48	36.0	17.6	< 1.0	700	32.4	0.0051	196
	All elevations relative to MSL		4/26/2010	18.17	11.72	418	96	97.6	9.86	14.8	37.1	46.6	150	< 0.1	0.63	0.132	< 0.10	0.39	0.578	0.44	58.0	12.0	< 1.0	780	56.2	0.0048	218
			1/27/2010	20.58	10.31	498	89	79.6	10.2	15.6	38.0	31.0	160	< 0.10	0.56	0.132	< 0.10	0.19	0.293	0.38	51.0	20.0	< 1.0	810	23.6	0.0043	234
			10/20/2009	25.80	5.09	448	100	97.1	12.8	16.4	37.9	36.6	180	< 0.10	0.56	0.168	0.16	< 0.10	0.18	0.42	42.6	16.0	< 1.0	760	19.5	0.0042	238
			8/19/2009	31.04	-0.15	426	160	101	18.9	93.2	29.1	64.4	36	< 0.10	0.93	NA	0.16	0.31	5.49	0.60	84.4	20	< 1.0	790	662	0.0038	267
			5/16/1983	14.20	16.59	770	60	60	NA	80	70	320	50	< 4	NA	ND	0.1	NA	0.02	NA	330	ND	ND	1,100	0.24	NA	NA

Des. by: CNT
Ckd. by: SSG 08.09.11

Oceano Community Services District
1655 Front Street, P. O. Box 599, Oceano, CA 93445 (805) 481-6730 FAX (805) 481-6836

Previous Photos

of

Sentry Well

Depth of Sentry Wells



Sentry Wells NO1, 2, and 3

Condition at Time of Test Exhibiting SW Characteristics

Monitoring Casings

Well in Great Disrepair. Note High Level of Contamination.

Access Port

Close Up of Contamination

Oceano Community Services District
1655 Front Street, P. O. Box 599, Oceano, CA 93445 (805) 481-6730 FAX (805) 481-6836

Current Photos

of

Sentry Well